

EMISOR:

TOYOTA MOTOR SALES de Mexico S de RL de CV

RFC: TMS010508RX0

Paseo de Tamarindos 400B, COL. BOSQUES DE LAS LOMAS
CP:05120 Cuajimalpa de Morelos, DF ,MEXICO

RECEPTOR:

ALECSA CELAYA S DE RL DE CV

RFC: ACE050912GZ0

ADOLFO LOPEZ MATEOS S/N LA LAJA 38130 , GTO, MEX

Cantidad	U Medida	Descripción	P Unitario	Importe
1.00	EA	SSP, COMPUTER, ENGIN	3396.20	3396.19
1.00	EA	FITTING KIT, TIRE PR	52.64	52.63
1.00	EA	CAP, RESERVE TANK	76.56	76.56
1.00	EA	PULLEY SUB-ASSY, IDL	486.59	486.58
1.00	EA	TENSIONER ASSY, V-RI	1617.50	1617.49
1.00	EA	VALVE SUB-ASSY, TIRE	574.70	574.69
1.00	EA	CYLINDER & KEY SET,	510.84	510.84
1.00	EA	CYLINDER & KEY SET,	510.84	510.84
1.00	EA	MIRROR ASSY, OUTER R	2223.87	2223.87
1.00	EA	PLUG, SOCKET	45.71	45.70
1.00	EA	GLASS SUB-ASSY, WIND	4955.61	4955.61
1.00	EA	LAMP ASSY, RR COMBIN	1428.24	1428.24
1.00	EA	ELEMENT SUB-ASSY, AI	197.01	197.01
1.00	EA	ELEMENT SUB-ASSY, AI	143.72	143.71
20.00	EA	GASKET	8.58	171.60
8.00	EA	PLUG, SPARK	29.04	232.32
1.00	EA	8PC AWM,SIENNA	1087.19	1087.18
1.00	EA	PANEL SUB-ASSY, FR D	5366.96	5366.95
1.00	EA	PANEL SUB-ASSY, RR D	4574.46	4574.46
1.00	EA	MOULDING SUB-ASSY, R	75.41	75.40
1.00	EA	MOULDING, FR DOOR WI	79.70	79.69
1.00	EA	BOOT, STEERING RACK,	112.53	112.53
1.00	EA	MOULDING, WINDSHIELD	365.64	365.64
10.00	EA	REPLACEABLE ELEMENT	41.25	412.50
1.00	EA	PAD KIT, DISC BRAKE	534.44	534.43
3.00	EA	ELEMENT SUB-ASSY, AI	143.72	431.14
4.00	EA	ELEMENT, AIR REFINER	152.79	611.16
6.00	EA	ELEMENT, AIR REFINER	152.79	916.74
10.00	EA	ELEMENT, AIR REFINER	152.79	1527.90
10.00	EA	FILTER, OIL	41.25	412.50
10.00	EA	FILTER S/A, OIL	41.25	412.50
1.00	EA	CYLINDER & KEY SET,	510.84	510.84
1.00	EA	COVER, FR DOOR OUTSI	53.79	53.79
1.00	EA	PAD, FR DOOR OUTSIDE	7.92	7.92
1.00	EA	TRANSMITTER, DOOR CO	749.10	749.10
1.00	EA	TRANSMITTER, TRANSP	271.10	271.09
1.00	EA	SUPPORT SUB-ASSY, FR	617.60	617.59
1.00	EA	RETAINER, CUSHION	57.26	57.25

SubTotal \$35812.18
 +IVA (16%) \$5729.95
 TOTAL \$41542.13



REGIMEN FISCAL :Régimen General de las Personas Morales FECHA TIMBRADO:2016-03-16T12:23:17

SELLO:

NqBn/ypc7qgBBhD/iZ1s/egmFvGPT2r9NT4G3tSEyHc7aCS/+F7qHvTI0ZDjnF6K+/a0GJL1DFLyqG9y8sn4WPY7OHIwtd1qfhm1Oqu2pLo
SIN6c9h7ailVJVZcWbXr5bZoXQukgzCr1sM/eOEoBzuOQHSCYmzWpSOBawnAYTqY=

SELLO SAT:

NUtnFzTHeBx73xUZ9z9wKwOROy0xkq/cbsH3L+JyfozBexl9xi6POTuYnECB08UIiRqqUy6snd27P2ot3WZRSTuqwyTDgmGibcgs5aKINg
Jcm7kGVzc3TQgBmYOv7G2XQCSMiZO6PW9GuzROY3hAiVotj30+S2UzYp3rKg+V8DA=

NUMERO CERTIFICADO SAT :00001000000300494998

CADENA ORIGINAL

||1.0|F0310D13-0B46-438B-B095-812D0FAABE29|2016-03-

16T12:23:17|NqBn/ypc7qgBBhD/iZ1s/egmFvGPT2r9NT4G3tSEyHc7aCS/+F7qHvTI0ZDjnF6K+/a0GJL1DFLyqG9y8sn4WPY7OHIwtd1qfh
m1Oqu2pLoSIN6c9h7ailVJVZcWbXr5bZoXQukgzCr1sM/eOEoBzuOQHSCYmzWpSOBawnAYTqY=|00001000000300494998||

Este documento es una representación impresa de un CFDI